

Operating Instructions
for
Handheld Pressure Measuring Devices
with External Pressure Sensors

Model: HND-P105



1. Contents

1. Contents.....	2
2. Note	3
3. Instrument Inspection.....	3
4. Regulation Use.....	3
5. Operating Principle.....	4
6. Electrical Connection	4
6.1 Mains Operation With Power Supply	4
7. Operation / Configuration / Adjustments	5
7.1 Safety Requirements	5
7.2 Connections.....	6
7.3 Display.....	6
7.4 Basic Operation	6
7.5 Configuration	7
7.6 Measuring Of Water Level – Display Unit [m]	8
7.7 Calibration Services.....	9
7.8 Pressure Connection To The Sensors.....	9
7.9 Error And System Messages	10
7.10 The Serial Interface	11
8. Maintenance	11
8.1 Battery Operation.....	11
9. Technical Information.....	12
10. Order Codes	13
10.1 Pressure sensors for HND-P105	13
10.2 Accessories	14
11. EU Declaration of Conformance.....	15

Manufactured and sold by:

Kobold Messring GmbH
Nordring 22-24
D-65719 Hofheim
Tel.: +49(0)6192-2990
Fax: +49(0)6192-23398
E-Mail: info.de@kobold.com
Internet: www.kobold.com

2. Note

Please read these operating instructions before unpacking and putting the unit into operation. Follow the instructions precisely as described herein.

The devices are only to be used, maintained and serviced by persons familiar with these operating instructions and in accordance with local regulations applying to Health & Safety and prevention of accidents.

When used in machines, the measuring unit should be used only when the machines fulfil the EC-machine guidelines.

3. Instrument Inspection

Instruments are inspected before shipping and sent out in perfect condition.

Should damage to a device be visible, we recommend a thorough inspection of the delivery packaging. In case of damage, please inform your parcel service / forwarding agent immediately, since they are responsible for damages during transit.

Scope of delivery:

The standard delivery includes:

- Handheld Pressure Measuring Devices with External Pressure Sensors
model: HND-P105
- Operating Instructions

4. Regulation Use

Any use of the Manual Pressure Measuring Devices with External and Integrated Pressure Sensors, model: HND-P105, which exceeds the manufacturer's specification may invalidate its warranty. Therefore, any resulting damage is not the responsibility of the manufacturer. The user assumes all risk for such usage.

5. Operating Principle

The KOBOLD manual pressure measuring devices HND-P105 are highly precise, compact pressure measuring devices that can be used universally. In conjunction with the appropriate external pressure sensors, precise measurement results over the entire measuring range can be achieved.

Various pressure sensors are available for a multitude of measuring tasks and special applications. The respective measurement task determines which combination is selected. Naturally, these first-rate KOBOLD-measuring units can display more than just pressure. All devices in this series allow for minimum/maximum value memory, hold function, automatic self-shut-off, or zero point offset entry for all connected pressure sensors.

6. Electrical Connection

6.1 Mains Operation With Power Supply



Warning: When using a power supply please note that operating voltage has to be 10.5 to 12 V_{DC}.

Do not apply overvoltage!! Cheap 12 V-power supplies often have excessive no-load voltage.

We, therefore, recommend using regulated voltage power supplies. Trouble-free operation is guaranteed by our power supply HND-Z002.

Prior to connecting the power supply to the mains make sure that the operating voltage stated at the power supply is identical to the mains voltage.

6.1.1 Connecting/Changing Sensors

Do not use unsuitable sensors. Connecting other devices/sensors as specified may cause a damage to the instrument and device/sensor! Switch off device before changing the sensor.

Connect sensor before switching on the device, otherwise the sensor may not be detected correctly. When connecting the sensor the connector may not lock correctly. In such case take the plug not at the casing but at the buckling protection at the end of the plug. If plug is entered correctly, it will slide in smoothly. To disconnect sensor do not pull at the cable but at the plug (to open locking mechanism).

7. Operation / Configuration / Adjustments

7.1 Safety Requirements

This device has been designed and tested in accordance with the safety regulations for electronic devices.

However, its trouble-free operation and reliability cannot be guaranteed unless the standard safety measures and special safety advises given in this manual will be adhered to when using the device.

1. Trouble-free operation and reliability of the device can only be guaranteed if the device is not subjected to any other climatic conditions than those stated under *9 Technical Information*.
2. Device and sensors have to be handled with care (don't throw, hit, etc.). Protect plugs and sockets from soiling.
3. If the device is transported from a cold to a warm environment condensation may cause in a failure of the function. In such a case make sure the device temperature has adjusted to the ambient temperature before trying a new start-up.
4. If device is to be connected to other devices (e.g. via serial interface) the circuitry has to be designed most carefully. Internal connection in third party devices (e.g. connection GND and earth) may result in not-permissible voltages impairing or destroying the device or another device connected.




Warning: If device is operated with a defective mains power supply (e.g. short circuit from mains voltage to output voltage) this may result in hazardous voltages at the device (e.g. at sensor socket or interface).

5. If there is a risk whatsoever involved in running it, the device has to be switched off immediately and to be marked accordingly to avoid re-starting. Operator safety may be a risk if:
 - there is visible damage to the device
 - the device is not working as specified
 - the device has been stored under unsuitable conditions for a longer period of time.

In case of doubt, please return device to manufacturer for repair or maintenance.

7.2 Connections



1. **Interface:** Connect to optically isolated interface adapter (accessory: GRS 3100, GRS 3105, USB 3100 or USB 3100N)
2. **Connections for pressure sensors** of the HND-PS-family
3. The **mains socket** is located at the left side of the instrument

7.3 Display

Units: an arrow points to the chosen measuring unit

SL: appears if sea-level-correction is activated

Tara: appears if tara-function is activated

main display: shows measuring value

secondary display: shows min-, max- or hold value

Logg: not used

7.4 Basic Operation

When switching on the device displayed “Corr”, if a sensor with activated offset or scale correction is connected.

On-/Off-Switch

1 ON/OFF

2 max

3 Tara

4 Set Menu

5 min

6 Store Quit

Tara: Calling of tara function

min/max: Showing the min- resp. max-memory

Store/Quit: Calling of hold function

Set/Menu: Calling of configuration

Tare Function: By pressing `Tara` (key 3) the displays will be set to 0. All measuring from then on will be displayed relatively to the set tare values. When the tare function is activated, the arrow “Tara” appears in the display. To deactivate tare function press `Tara` for >2 seconds. **Please note: Activating/deactivating tara clears the max-&min-memories.**

Max Memory: Pressing `max` (key 2) shows the maximum of the measured values. Pressing it again hides it. To clear the max memory press key `max` for >2 seconds.

Min Memory: Pressing `min` (key 5) shows the minimum of the measured values. Pressing it again hides it. To clear the min memory press key `min` for >2 seconds.

Hold Function: By pressing `Store/Quit` (key 6) the last measuring value will be held in the secondary display. Pressing it again hides it.

Zero-Point Adjustment: If there is no pressure or zero-pressure (absolute) applied to the pressure ports the device will display 0. If there is a permanent deviation (and device is operated under steady conditions), a permanent zero point adjustment can be carried out. To carry out the adjustment press key 3 for approx. 5 seconds. (Auto Null will be displayed shortly). The adjustment is done via the OFFSET-value of the sensor (referring configuration menu). Please note: A zero-point adjustment can only be carried out if the difference between the value on display is less than 500 digits!

To recall the manufacturer`s calibration press button 3 for approx. 15 seconds.

Note: If a zero-point adjustment was carried out, this will be signalled by the short displaying of “Corr” when switching on the device.

7.5 Configuration

To change device settings, press **Menu** (key 4) for 2 seconds. This will call the configuration menu.

Pressing key **Menu** jumps between the parameters.

The parameters can be changed with \blacktriangle (key 2) or \blacktriangledown (key 5).

Quit (key 6) finishes the configuration and returns to standard measuring operation.


7.5.1 Unit: Choice Of The Display Unit



Choose the desired display unit, the referring unit is displayed by means of a functional arrow in the display. The selection is permanently stored in the sensor, therefore after reconnecting the sensor the unit will instantly reappear. The choice depends on the used sensor.

7.5.2 Sea Level Correction For Absolute Pressure Sensors

The device displays the absolute pressure measured at the sensor. This is not necessarily the same like the values given by weather stations! The weather stations' values are pressure at sea level. Usually the sensor is placed above sea level and therefore, if the value at sea level (zero) is to be measured, the pressure loss resulting from the actual level above zero has to be considered!



- To correct activate the „Sea-Level-Function“:
Select „on“ in the menu „SL“ with \blacktriangle (key 2) or \blacktriangledown (key 5).



- Jump to the next parameter „Alti“ by pressing **Menu** (key 4).
Then enter the altitude above sea level of the sensor's location in meters and leave the configuration by pressing **Quit** (key 6)

If the sea level correction is active this will be shown by the functional arrow „SL“ in the display, the device now displays the absolute pressure at sea level (zero).

7.5.3 P.oFF: Auto Power Off Time



The device will be automatically switched off if no key is pressed/no interface communication takes place for the time of the power off time. The power off time can be set to values between 1 and 120 min. It can be completely deactivated by setting the parameter to ,P.oFF = oFF“.

7.5.4 Adr: Base Address of Interface



Up to 10 devices of the HND- handheld-family can be connected to a serial interface at once (depending on interface converter, e.g. HND-P...: 5 devices). To get access to each device the base addresses of the devices have to be different. For example choose 01 for the first, 11 for the second device and so on.

7.5.5 OFFS: Adjusting Sensor Zero Displacement

A zero displacement can be carried out for the measured value:

$$\text{value displayed} = \text{value measured} - \text{offset}$$

Standard setting: 'off' = 0.0, i.e. no zero displacement will be carried out. Together with the scale correction (see below) this factor is mainly used to compensate for sensor deviations. Input is in the display unit.

7.5.6 SCAL: Adjusting Sensor Scale

The scale of the measuring can be influenced by this setting (factor is in %):

$$\text{displayed value} = \text{measured value} * (1 + \text{Scal}/100)$$

Standard setting: 'off' = 0.000, i.e. value is not corrected. Together with the zero displacement (see above) this factor is mainly used to compensate for sensor deviations.

7.6 Measuring Of Water Level – Display Unit [m]

(only for devices with ,m' printed below the display)

When using a suitable waterproof pressure sensor the unit [m] for meters of water can be set in the menu "Unit". 10 m of water are roughly 1 bar over pressure. Measurements can be made e.g. like described below :

- With abs. pressure sensor (SL oFF!): Press ,Tara' when sensor is at ambient air and then bring sensor to the depth to be measured. The display shows now the depth in [m].
- With rel pressure sensor: bring tube connection for lower press. in contact to ambient air by means of a tube (no water contact!) and bring the sensor with its open press. connection for higher pressure to water depth to be measured (display and is compensated for pressure changes in ambient air).

7.7 Calibration Services

Calibration certificates – DKD-certificates – other certificates:

If device should be certified for its accuracy, it is the best solution to return it with the referring sensors to the manufacturer.

Only the manufacturer is capable to do efficient recalibration if necessary to get results of highest accuracy!

7.8 Pressure Connection To The Sensors

The device is designed to be connected to the sensors of the HND-PS...-series without a new calibration being necessary. Therefore a great variety of replaceable sensors of e.g. –1.999...2.500 mbar relative up to 0...400.0 bar absolute pressure can be connected to the device (*p.r.t. chapter 10.1 Pressure sensors*)

7.8.1 Relative Pressure Sensors

- **For measurements of over- or under pressure:**

Connect plastic tube with internal dia of 4 mm to pressure port "B". Port "A" will not be used!

Pressure sensors HND-PS01, -PS02 and –P03 allow for measurements of under pressure up to the entire over pressure measuring range by re-plugging the tube to pressure port "A". Please note that all values are displayed as positive values. No minus sign will be shown. (Example for HND-PS02: For tube connection "B" the measuring range covers -19.99 to 25.00 mbar. If you replug to port "A" under pressure measurements down to -25.00 mbar could be carried out with the display showing the value 25.00 (no minus sign).

- **For measurements of pressure differences:**

Connect both plastic tubes with an internal dia of 4 mm to pressure port "B" and "A"; make sure to apply higher pressure to port "B".




7.8.2 Absolute pressure sensors:

Connect plastic tube with an internal dia of 4 mm to pressure port "A". (Port "B" is not used.)

7.8.3 Stainless steel pressure sensors:

For measurements of over-, under- or absolute pressure screw sensor to G1/4" pressure terminal or plug plastic tube to a suitable adapter.

7.9 Error And System Messages

Display	Meaning	What to do?
	Low battery power, device will only continue operation for a short period of time	Replace battery
	Battery empty	Replace battery
	Mains operation without battery: wrong voltage	Check power supply, replace it when necessary
 or Err.9	No sensor connected	Switch off device and connect sensor
	Connected sensor or device defective	If second sensor available, check if device is ok. Return defective device/sensor to manufacturer for repair
	Measured value far out of allowable range	Check: pressure not within sensor range?
No display or confused characters, device does not react on keypress	Battery empty	Replace battery
	Mains operation without battery: wrong voltage or polarity	Check power supply, replace it when necessary
	System error	Disconnect battery and power supplies, wait shortly, then reconnect
	Device defective	Return to manufacturer for repair
Err.1	Measured value above allowable range	Check: pressure not within sensor range? -> measuring value to high!
	Sensor defective	Return to manufacturer for repair
Err.2	Measured value below allowable range	Check: pressure not within sensor range? -> measuring value to low!
	Sensor defective	Return to manufacturer for repair
Err.3	Display range overflow	Check: value above 19999->to high to be displayed
Err.4	Display range underflow	Check: display below -19999 (Tara?)-> to low!
Err.11	Value could not be calculated	Choose different unit
	Calculation overflow happened	Choose different unit
Err.7	System error	Return to manufacturer for repair
----	Sensor not present/recognised	Connect suitable sensor
	Could not calculate value	

7.10 The Serial Interface

By means of the serial interface and a suitable electrically isolated interface adapter (HND-Z031 or HND-Z032) the device can be connected to a computer for data transfer. To avoid transmission errors, there are several security checks implemented e.g. CRC.

The following standard software packages are available:

- **BUS-EBS9M:** 9-channel software to display the measuring values




Note: The measuring display range values read back from the interface are always in the selected measurement unit (mbar, bar...)!

Supported functions:

Code	Name/Function	Code	Name/Function
0	Read measurement value	200	Read min display range
3	Read system state	201	Read max display range
6	Read min value	202	Read display range - unit
7	Read max value	204	Read display range – decimal point
12	Read ID number	208	Read # of channels
176	Read min measuring range	214	Read Scale adjustment
177	Read max measuring range	216	Read Offset adjustment
178	Read measuring range unit	222	Read power off time (Conf.-P.oFF)
179	Read measuring range decimal point	223	Set power off time (Conf.-P.oFF)
180	Read kind of measuring of sensor	240	Reset
199	Read kind of measuring of display	254	Program version

8. Maintenance

8.1 Battery Operation

If  and 'bAt' are shown in the secondary display the battery has been used up and needs to be replaced. The device will, however, operate correctly for a certain amount of time. If 'bAt' is shown in the upper display the voltage is too low to operate the device; the battery has been completely used up. The battery has to be taken out, when storing device above 50 °C.



Please note: We recommend to take out battery if device is not used for a longer period of time!

9. Technical Information

Measuring ranges:

Display range:	-19999 ... +19999 digit, depending on connected sensor
Resolution:	depending on connected sensor
Pressure units:	mbar, bar, kPa, MPa, mmHg, PSI, mH ₂ O
Accuracy: (typ.)	± 0,1 % F.S. (at nominal temperature)
Measuring rate:	4 meas./sec
Nominal temperature:	25 °C

Sensor:

All sensors of the HND-PS-series without calibration can be connected.

Connection:

Mini-DIN-Socket with locking mechanism
The sensor will automatically be detected, the measurement range settings are set referring to sensor data

Additional Functions:

Power-Off-Function:

Device will be automatically switched off if no key is pressed/no interface communication takes place for the time of the power-off delay. The power-off delay can be set to values between 1 and 120 min.; it can be completely deactivated.

Display:

2 four-digit LCDs (12.4mm high and 7mm high) for measuring values, and for min/max memories, hold function, etc. As well as additional functional arrows.

Pushbuttons:

6 membrane keys

Interface:

Serial interface (3.5 mm jack) can be connected to HND-Z031 or HND-Z032 to RS232 or USB interface of a PC via electrically isolated interface adapter.

Power supply:

9 V-battery, type: IEC 6F22 (included in the scope of delivery)
As well as additional d.c. connector (diameter of internal pin 1.9 mm) for external 10.5-12V direct voltage supply. (suitable power supply: GNG10/3000)

Power consumption:

<1.6 mA

Low battery warning:

`bAt`

Housing:

impact-resistant ABS, membrane keyboard, transparent panel, Front side IP65

Dimensions:

142 x 71 x 26 mm (LxWxD)

Weight:

approx. 150 g

Working temperature:

-25...+50 °C

Allowable rel. humidity:

0...95%RH (not condensing)




Storage temperature:

-25...+70 °C

10. Order Codes

Order-no.	Housing design
HND-P105	1 x pressure sensor input, standard

10.1 Pressure sensors for HND-P105

Measuring range	Accuracy	Resolution	Overload	Working-Temperature	Connection	Order-no.
1.999...2.500 mbar	$\pm 0.2\%$ f.s. / $\pm 1.0\%$ f.s.*	0.001 mbar	max. 200 mbar	0...+50 °C	Nylon spigot for hose 6 x1 mm 	HND-PS01**
19.99...25 mbar	$\pm 0.2\%$ f.s. / $\pm 0.5\%$ f.s.*	0.01 mbar	max. 300 mbar			HND-PS02**
199.9...350.0 mbar	$\pm 0.2\%$ f.s. / $\pm 0.4\%$ f.s.*	0.1 mbar	max. 1 bar			HND-PS03**
1000...2000 mbar		1 mbar	max. 4 bar			HND-PS04**
-1...10 bar		10 mbar	max. 10.34 bar			HND-PS05**
0...1300 mbar abs.		1 mbar	max. 4 bar abs.			HND-PS06**
0...2000 mbar abs.		10 mbar	max. 10 bar abs.			HND-PS07**
0...7.00 bar abs.		0.1 mbar	max. 1.4 bar			HND-PS08**
0...350.0 mbar rel.	$\pm 0.2\%$ f.s. / $\pm 0.4\%$ f.s.*	1 mbar	max. 4 bar abs.	0...+70 °C	G ¼ male, stainless steel 	HND-PS09
0...1000 mbar abs.			max. 14 bar abs.			HND-PS10
0...3500 mbar abs.			max. 14 bar rel.			HND-PS11
0...3500 mbar rel.			max. 28 bar abs.			HND-PS12
0...7000 mbar abs.		10 mbar	max. 140 bar abs.			HND-PS13
0...35.00 bar abs.			max. 280 bar abs.			HND-PS14
0...70.00 bar abs.		0.1 bar	max. 600 bar abs.			HND-PS15
0...160.0 bar abs.						HND-PS16
0...250.0 bar abs.						HND-PS17
0...400.0 bar abs.						HND-PS18
0...1000 mbar abs	$\pm 0,2\%$ ME / $\pm 0,4\%$ ME*	1 mbar	max. 5 bar abs	0...+70°C	G ½ male 	HND-PA20
0...2500 mbar abs			max. 10 bar abs			HND-PA21
0...4000 mbar abs			max. 17 bar abs			HND-PA22
0...6000 mbar abs			max. 35 bar abs			HND-PA23

* in the range from 0 to +50 °C

** Pressure sensors HND-PS01 up to HND-PS08 are only suitable for air and non corrosive/non ionizing gases and liquid.

10.2 Accessories

Order-no.	Description
HND-Z002	Plug power supply unit (220/240 V, 50/60 Hz), 10.5 V/10 mA
HND-Z011	Equipment protective housing bag, nappa leather, with 1 cut-out for round sensor connection
HND-Z012	Equipment protective housing bag, nappa leather, with 2 cut-outs for round sensor connection
HND-Z021*	Case with recess (275 x 229 x 83 mm)
HND-Z022*	Universal case with egg crate foam (275 x 229 x 83 mm)
HND-Z023*	Large case with recess (394 x 294 x 106 mm)
HND-Z031	Interface converter on RS232, galvanically isolated
HND-Z032	Interface converter on USB, galvanically isolated
HND-Z033	Adapter RS232 converter on USB- interface
HND-Z034	Windows software for setting and data read- and print-out of instruments of the HND- series with logger function
BUS-S20M	Software for recording measuring data on a PC for 20 modules, for devices of the HND-series without logging function
HND-Z081	Double nozzle for hose 6.4 on hose 6.4
HND-Z082	Hose clamp for hose 6.4
HND-Z083	Adapter made of brass for G ½ internal threads on hose 6.4
HND-Z084	PVC-hose (5 bar), 6 mm external / 4 mm internal
HND-Z085	PE-hose (10 bar), 6 mm external / 4 mm internal
HND-Z086	PU-hose (9 bar), 6 mm external / 4 mm internal
HND-Z087	PA-hose (25 bar), 6 mm external / 4 mm internal

* Please pay attention to instrument dimensions

More accessories on request

11. EU Declaration of Conformance

We, KOBOLD Messring GmbH, Hofheim-Ts, Germany, declare under our sole responsibility that the product:

**Handheld Pressure Measuring Devices with External Pressure Sensors
Model: HND-P105**

to which this declaration relates is in conformity with the standards noted below:

EN 61326-1:2013

Electrical equipment for measurement, control and laboratory use - EMC requirements - Part 1: General requirements

EN 50581:2012

Technical documentation for the assessment of electrical and electronic products with respect to the restriction of hazardous substances

Also the following EU guidelines are fulfilled:


2014/30/EU
2011/65/EU

Electromagnetic compatibility
RoHS (category 9) industrial monitoring and control instruments, compliant, no CE-marking for the transitional period until 2017

Hofheim, 01. Dec. 2016



H. Peters
General Manager



M. Wenzel
Proxy Holder